



AUTOPARTS.REPAIR
AUTOMOTIVE ELECTRONIC PART REPAIR SERVICES

2018 Services Catalog

Repair Services & Remanufactured
PORSCHE Electronic Auto Parts

AUTOPARTS.REPAIR

ELECTRONIC AUTOMOTIVE PART REPAIR SERVICES

Repair Services & Remanufactured PORSCHE Electronic Auto Parts

Name	Models Covered	Price	
1980-1989 Porsche 911 (early) Controller Module Repair Service	: Porsche 911 ,993, Porsche Convertible	\$389.00	
1980-1989 Porsche 911 (early) Speedometer Repair Service	: Porsche 911	\$389.00	
1995-1998 Porsche 911 (993) Controller Module Repair Service	: Porsche 911 ,993,	\$389.00	
1995-1998 Porsche 911 (993) Controller Module Repair Service	: Porsche 911 ,993, Porsche Convertible	\$389.00	
1995-1998 Porsche 911 (993) Controller Module Repair Service	: Porsche 911 ,993,	\$389.00	
1995-1998 Porsche 911 (993) Tachometer Repair Service	: Porsche 911 ,993,	\$389.00	
1995-1998 Porsche 911 (993) Tachometer Repair Service	: Porsche 911 ,993,	\$389.00	
1995-1998 Porsche 911 (993, 964) Motor Electronic Repair Service	: Porsche 911 ,993,	\$459.00	
1998-2005 Porsche 911 (996) Instrument Cluster Repair Service	: Porsche 911 ,996,	\$389.00	

AUTOPARTS.REPAIR

ELECTRONIC AUTOMOTIVE PARTS REPAIR SERVICE

1998–2005 Porsche Boxster (986) Instrument Cluster Repair Service	: Porsche Boxster ,986,Boxster 550 Spyder	\$389.00	
2002–2010 Porsche Cayenne (955) Instrument Cluster Repair Service	: Porsche Cayenne ,955,	\$379.00	
2002–2010 Porsche Cayenne (955) Instrument Cluster Repair Service	: Porsche Cayenne ,955,	\$379.00	
2005-2012 Porsche 911 (997) Instrument Cluster Repair Service	: Porsche 911 ,997,	\$389.00	
2005-2012 Porsche 911 (997) Instrument Cluster Repair Service	: Porsche 911 ,997,	\$389.00	
2005-2012 Porsche 911 (997) Instrument Cluster Repair Service	: Porsche 911 ,997,	\$389.00	
2005-2012 Porsche Boxster (987) Instrument Cluster Repair Service	: Porsche Boxster ,987,Boxster 550 Spyder	\$389.00	
2005-2012 Porsche Boxster (987) Instrument Cluster Repair Service	: Porsche Boxster ,987,Boxster 550 Spyder	\$389.00	
2005-2012 Porsche Boxster (987) Instrument Cluster Repair Service	: Porsche Boxster ,987,Boxster 550 Spyder	\$389.00	